

M/023/007

From: Doug Jensen
To: Pam Grubaugh-Littig, Wayne Hedberg
Date: 9/19/00 7:18AM
Subject: North Lily Update

Call from Bob Bayer today

Liner repair contractor to be onsite today to assess if the liner in the northwest corner can be repaired.

He hasn't had word yet as to the outcome of this visit.

New back-up pump burned up just after it was installed. Walt has "borrowed" a couple of pumps to help take up the slack for the moment. One is a 450 gpm pump to be placed in the overflow pond for pump back. This will be operated on a cyclic basis and the flow rate will assure that the pond levels will stay well below the tears in the liner. A second pump (200gpm) will be installed and used to pump solutions to the overflow pond misters. This should provide a better pressure to this system and hopefully accelerate the evaporation in this area.

Walt thought that the weir reading was .11", which is a drop from the .125" reading on 9/11, but Bob says Elwin's weekly report show the reading is still at .125", so much for consistency.

Repairs on the ditch margin are done waiting for testing by Walt.

Message machine cut off at this point, more details later.

Joelle please file this in **M/023/007**

CC: Joelle Burns